

Inspection Report

Test Date	Identifier	Description	Class	Test Interval (mnts)	Vis Test	Elec Test	Status	Next Test Date
-----------	------------	-------------	-------	----------------------	----------	-----------	--------	----------------

Owner: Demo Company
 123 Demoville
 Demo SA 5000
 Phone: 088000000

 demo@demo.com.au

06/05/12	1000	Kettle - Lunch room	I	12	✓	✓	Passed	06/05/13
22/05/12	1001	Computer - Office 1	I	60	✓	✓	Passed	22/05/17
22/05/12	1002	Extention cord - Lunch Room	Lead	12	✓	✓	Passed	22/05/13
22/05/12	1003	Clock - Show Room	I	12	✓	✓	Passed	22/05/13
22/05/12	1004	Radio - Reception	I	12	✓	✓	Passed	22/05/13
22/05/12	1005	Power Board - Lunch Room	EPOD	12	✓	✓	Passed	22/05/13
22/05/12	1006	Power Board - Reception	EPOD	12	✓	✓	Passed	22/05/13
22/05/12	1007	Toaster	I	12	✓	✓	Passed	22/05/13
22/05/12	1008	Drill - Workshop	I	12	✓	✓	Passed	22/05/13
22/05/12	1009	Portable RCD - Workshop	RCD	6	✓	✓	Passed	22/11/12
22/05/12	1010	Grinder - Workshop	II	6	✓	✓	Passed	22/11/12
22/05/12	1011	Speakers - Office 1	I	12	✓	✓	Passed	22/05/13
22/05/12	1012	Extention cord - Workshop	Lead	12	✓	✓	Passed	22/05/13
22/05/12	1013	Phone Charger - Office	II	12	✓	✓	Passed	22/05/13
22/05/12	1014	Phone Charger - Reception	II	12	✓	✓	Passed	22/05/13
22/05/12	1015	Extention cord - Lunch Room	Lead	12	x	✓	Failed	22/05/12
<i>Visual test failed due to cord damage.</i>								
22/05/12	1016	Phone Charger - Workshop	II	12	x	x	Failed	22/05/12
<i>Item failed both visual & electrical test</i>								

Tester's Name (and License No):

Test Count: 17

Items Passed: 15

Items Failed: 2

Items Not Found: 0